

ECY 050-1-20

Driller's Log

B&W Well Drilling

Rotary
Completed 1979

Location: 29/3-8J

Owner: Donna Schultz

Well depth: 372'

Static water level: 282.6'

Formation:

0-2	Top soil
2-25	Hardpan, grey
25-130	Sand, grey
130-140	Fine sand with water, brown
140-150	Fine sand with water, grey
150-235	Clay, grey
235-270	Fine sand with water, grey
270-350	Clay, grey
350-372	Medium sand with water, grey

Pump test:

15 g.p.m.
3' drawdown after 4 hrs.

WELL DRILLER'S STATEMENT

This well was drilled under my supervision and this report is true to the best of my knowledge and belief.

B & W DRILLING CO.

P.O. Box 55, FREEDOM, MO 64003

John A. Lee

8/6/79